

**Warning** To avoid possible electric shock or personal injury, and to avoid possible damage to the Meter or the equipment under test, adhere to the following rules:  
1. Before using the Meter, inspect the case. Do not use the Meter if it is damaged or the case cracks or part of the case is removed. Look for the insulation around the connectors. Pay attention to the insulation around the plastic. Pay attention to the insulation around the connectors. Do not use the test leads for damaged insulation.

**Caution** Before testing the battery as soon as the battery indicator appears. With a low battery, the Meter might produce false readings that can lead to electric shock and personal injury. Remove the connection between the testing leads and the circuit being tested, and turn the meter power off before opening the Meter case. When servicing the Meter, use only the same model number or identical electrical components. The internal circuit of the Meter shall not be altered and the Meter shall not be modified in any way. The Meter switch should be used to clean the surface of the Meter when it has been used to prevent the surface of the Meter from corroding. No abrasive and solvent should be used to clean the surface of the Meter when it has been used to prevent the surface of the Meter from corroding. Turn the Meter power off when it is not in use and take out the battery when not using for a long time. Constantly check the battery as it may leak when it has been used for some time, and the Meter power off when it is not in use and store the Meter in an environment of high humidity, explosive, inflammable and strong magnetic field. The performance of the Meter may deteriorate after dampened.

**Do not use the test leads for your measurements. Use the proper terminals, function, and range over 60V in DC or 30V ms in AC, special care should be taken for there is danger of electric shock. When working at an effective voltage over 60V in DC or 30V ms in AC, special care should be made during measurement is conducted to prevent damage of the Meter.**

**When the Meter is stored in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field, the test leads, keep your fingers behind the test leads, and store the Meter in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field. Do not store the Meter in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field. Turn the Meter power off when it is not in use and store the Meter in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field. Do not use the test leads for your measurements. Use the proper terminals, function, and range over 60V in DC or 30V ms in AC, special care should be taken for there is danger of electric shock. When working at an effective voltage over 60V in DC or 30V ms in AC, special care should be made during measurement is conducted to prevent damage of the Meter.**

**Use the proper terminals, function, and range over 60V in DC or 30V ms in AC, special care should be taken for there is danger of electric shock. When working at an effective voltage over 60V in DC or 30V ms in AC, special care should be made during measurement is conducted to prevent damage of the Meter.**

**Discard circuit power and discharge all behind the test leads, keep your fingers behind the test leads, and store the Meter in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field. Do not use the test leads for your measurements. Use the proper terminals, function, and range over 60V in DC or 30V ms in AC, special care should be taken for there is danger of electric shock. When working at an effective voltage over 60V in DC or 30V ms in AC, special care should be made during measurement is conducted to prevent damage of the Meter.**

**When the Meter is stored in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field, the test leads, keep your fingers behind the test leads, and store the Meter in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field. Do not store the Meter in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field. Turn the Meter power off when it is not in use and store the Meter in an environment of high temperature, humidity, explosive, inflammable and strong magnetic field. Do not use the test leads for your measurements. Use the proper terminals, function, and range over 60V in DC or 30V ms in AC, special care should be taken for there is danger of electric shock. When working at an effective voltage over 60V in DC or 30V ms in AC, special care should be made during measurement is conducted to prevent damage of the Meter.**

Model	DV	ACV	DCA	Ω	HFE	DCN	C
700D	✓	✓	✓	✓	✓	✓	✓
700C	✓	✓	✓	✓	✓	✓	✓
700B	✓	✓	✓	✓	✓	✓	✓

**700 Series Multimeters Function Table**

The following table lists the functions available for each model of the 700 Series Multimeters. The '✓' symbol indicates that the function is present in that specific model.

**DC & AC VOLTMAGE MEASUREMENT**  
DC VOLTAGE RESOLUTION ACCURACY  
RANGE RESOLUTION ACCURACY  
1. Connect red test lead to "VΩmA" jack, Black lead to "COM" jack.  
2. Set RANGE switch to desired VOLTAGEx range, if the voltage to be measured is not known before hand, set switch to the highest range and reduce it until satisfactory reading is obtained.  
3. Connect test leads to device or circuit being measured.  
4. Turn on power of the device or circuit being measured.

DC CURRENT	RESOLUTION	ACCURACY
1A	10mA	(1.0% + 15)
10A	100mA	(1.0% + 15)
100A	1mA	(0.5% + 3D)
2000A	100μA	(1.8% of rdg + 2D)

**TEMPERATURE INSTRUMENTS**  
TEMPERATURE WITH K-TYPE PROBE  
RANGE RESOLUTION ACCURACY  
1.0°C to 1370°C (1.5% + 15)  
150°C to 150°C (1.0% + 4)  
40°C to 150°C (1.0% + 4)  
150°C to 150°C (1.0% + 4)  
200°C to 200°C (1.0% of rdg + 10D)  
200KΩ to 200KΩ (1.0% of rdg + 4D)  
200Ω to 200Ω (1.0% of rdg + 10D)  
200KΩ to 200KΩ (1.0% of rdg + 10D)  
200Ω to 200Ω (1.0% of rdg + 10D)  
MAXIMUM OPEN CIRCUIT VOLTAGE: 3V.  
OVERLOAD PROTECTION: 15 seconds maximum.  
OVERLOAD PROTECTION: 15 seconds maximum.

AC VOLTAGE	RESOLUTION	ACCURACY
750V	100mV	(2.0% of rdg + 10D)
200V	100mV	(2.0% of rdg + 10D)
200Ω to 200Ω (1.0% of rdg + 10D)	10Ω	(1.0% of rdg + 10D)
200Ω to 200Ω (1.0% of rdg + 10D)	1Ω	(1.0% of rdg + 10D)
200Ω to 200Ω (1.0% of rdg + 10D)	100Ω	(1.0% of rdg + 10D)
200Ω to 200Ω (1.0% of rdg + 10D)	1kΩ	(1.0% of rdg + 10D)
200Ω to 200Ω (1.0% of rdg + 10D)	200kΩ	(1.0% of rdg + 10D)
200Ω to 200Ω (1.0% of rdg + 10D)	2MΩ	(1.0% of rdg + 10D)
200Ω to 200Ω (1.0% of rdg + 10D)	200MΩ	(1.0% of rdg + 10D)

**RESISTANCE**  
RESISTANCE  
RANGE RESOLUTION ACCURACY  
0.1Ω to 1Ω (1.0% of rdg + 10D)

measured voltage value will appear on Digital Display along with the voltage polarity.

#### DC CURRENT MEASUREMENT

- Red lead to "VΩmA". Black lead to "COM" (for measurements between 200mA and 10A connect red lead to "10A" jack with fully depressed.)
- Set RANGE switch to desired DCA range.
- Open the circuit to be measured, and connect test leads INSERIES with the load in with current is to measure.
- Read current value on Digital Display.
- Additionally, "10A" function is designed for intermittent use only. Maximum contact time of the test leads with the circuit is 15 seconds, with a minimum intermission time of seconds between tests.

#### RESISTANCE MEASUREMENT

- Red lead to "VΩmA". Black lead to "COM".
- Set RANGE switch to desired Ω range.
- If the resistance being measured is connected to a circuit, turn off power and discharge all capacitors before measurement.
- Connect test leads to circuit being measured.
- Read resistance value on Digital Display.

#### DIODE MEASUREMENT

- Red lead to "VΩmA", Black lead to "COM".

- Set RANGE switch to "HFE" range.
- Connect the red test lead to the anode of the diode to be measured and black test lead to cathode.
- The forward voltage drop in mV will be displayed. If the diode is reversed, figure "1" will be shown.

#### TRANSISTOR hFE MEASUREMENT

- Set RANGE switch to the hFE range.
- Determine whether the transistor is PNP or NPN type and locate the Emitter, Base and Collector leads. Insert the leads into the proper holes of the hFE Socket on the front panel.
- The meter will display the approximate hFE value at the condition of base current 10µA and  $V_{CE}2.8V$ .

#### TEMPERATURE MEASUREMENT

- RANGE switch to TEMP position, it will display room temperature in °C value.
  - Connect the K-type thermoelectric couple to "VΩmA" and "COM" jacks.
  - The display will read Temperature value °C.
- NOTE: The TP01 K-type thermocouple Max. Operating temperature of Probe: 250°C (300°C short-term). The sensor supplied with the instrument is an ultra fast response naked bead thermocouple suitable for many general purpose applications.

- AUDIBLE CONTINUITY TEST
  - Set RANGE switch to "L-L" range.
  - Connect the red test lead to the anode of the diode to be measured and black test lead to cathode.
  - The forward voltage drop in mV will be displayed. If the diode is reversed, figure "1" will be shown.

#### TEST SIGNAL USE

- Set RANGE switch to "L-L" range.
  - A test signal (50Hz) appears between "VΩmA" and "COM" jack, the output voltage is approx 5V p-p with 50KΩ impedance.
- NOTE: OVERLOAD PROTECTION: 15 seconds maximum.


#### BATTERY AND FUSE REPLACEMENT

Fuse rarely need replacement and blow almost always as a result of operator error.

If appears in display, it indicates that the battery should be replaced.

To replace battery & Fuse (F500mA/250V) removes the 2 screws in the bottom of the case, simply remove the old, and replace with a new one. Be careful to observe polarity.

- ACCESSORIES**
  - Operator's instruction manual
  - Set of test leads
  - Gift box
  - TP01 K-type thermoelectric couple (700C only)
  - 9-volt battery, NEDA 1604 6F22 type.



PN: 31.11.7006

- 9 -

## OPERATOR'S INSTRUCTION MANUAL

# 700 SERIES DIGITAL MULTIMETER

### WARNING

READ AND UNDERSTAND THIS MANUAL BEFORE USING THE INSTRUMENT.

Failure to understand and comply with the WARNINGS and operating instructions can result in serious or fatal injuries and/or property damage.